

Message

---

**From:** Dan Johnson [DanJohnson@florencecopper.com]  
**Sent:** 11/13/2018 4:15:23 PM  
**To:** Rumrill, Nancy [Rumrill.Nancy@epa.gov]  
**CC:** Albright, David [Albright.David@epa.gov]  
**Subject:** Temperature Logs for R-08 during cementing of casings  
**Attachments:** ATT00001.txt; R-08-GCT-FIELD-11-17-17.pdf; R-08-GCT FIELD-4-6-18.pdf

Good Morning Nancy,

Attached are the temperature logs for R-08 during the installation of the cement seals. They may be helpful for your consultants review. The first attachment is the installation of the large outer steel casing and the second attachment is the seal between the outer steel casing and the fiberglass well casing.

Our thoughts and prayers are with all of you up there and hopefully the fires will be contained and put out soon.

Best Regards,

**Dan Johnson** VP | General Manager



Florence Copper Inc.  
1575 W. Hunt Highway Florence AZ USA 85132  
C 520-233-1930 T 520-374-3984 F 520-374-3999  
E [danjohnson@florencecopper.com](mailto:danjohnson@florencecopper.com) Web [florencecopper.com](http://florencecopper.com)

---

\*Notice Regarding Transmission

This message is intended only for the person(s) to whom it is addressed and may contain information that is privileged and confidential. If you are not the intended recipient, you are hereby notified that any dissemination or copying of this communication is prohibited. Please notify us of the error in communication by telephone (778-373-4533) or by return e-mail and destroy all copies of this communication. Please note that any views or opinions presented in this email are solely those of the author and do not necessarily represent those of Taseko Mines Limited or any affiliated or associated company. The recipient should check this email and any attachments for the presence of viruses. Neither Taseko Mines Limited nor any affiliated or associated company accepts any liability for any damage caused by any virus transmitted by this email. Thank you."